



Notice to Mariners – 03-2022

07th May 2022

Inner Harbour Channel Marker No. 1

Inner Harbour Channel Marker No. 1 – West Side.

Position 58⁰ 12.574'N 006⁰ 23.446'W.

Cat 2 – Aton No. A 3980.55 – Fl R 2S.

Channel marker pole missing from station.

Mariners, port, and marina users are advised to navigate with caution.

William Morrison
Harbourmaster

